

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA

Division Director

Minerals Inspection Report

Reviewed

Report Date: 04/08/2015

Mine Name: County Canyon Shale		Permit Number:	M/023/0024	4 Mine Status:	Active
Operator Name: Ash Grove Cement Company		Inspection Date:	04/07/2015	Permit Fees:	Paid
Inspe	ctor(s): Wayne Western	Inspection Time:	9:50 - 10:00 a	am Bond Amount:	\$166,000
Attendee(s): Josh Nelson Weath				Bond Escalation:	07/19/2017
Inspection Purpose: Routine inspection				Prior Inspection:	03/11/2014
Conclusions and Recommendations The pit was idle in 2013 and 2014. The Operator did haul material off site during those years. The Operator plans on resuming operations in 2015.					
Elements of Inspection				Evaluated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds			\boxtimes	
	The fees and bond are current				
2.	Public Safety (shafts, adits, trash, signs, highwalls)				
	There were several tire tracks in the area indicating that the public will access the site. Last Sunday was Easter. During Easter weekend the Little Sahara Sand Dunes receives 20,000 to 30,000 visitors. Many of the visitors look for places to camp in the area. There are no underground openings or other significant hazards at the site.				
3.	Protection of Drainages/Erosion Control			\boxtimes	
	Runoff is contained in the pit.				
4.	Deleterious Material			\boxtimes	
	No mining materials are on site.				
5.	Roads (maintenance, surfacing, dust control, safety)			\boxtimes	
	Roads are in good working condition.				
6.	Reclamation				
	No reclamation occurred at the site in 2014.				
7.	Backfilling/Grading (trenches, pits, roads, highwalls, sha	fts)			
8.	Soils				
9.	Revegetation				
10.	Other				
Inspector's Signature:					

CC: jmccarth@blm.gov

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/- Inspection Summary/Inspection Forms/Inspection form 3.0.1.pdf



M/023/0024 Mine: Page 2 of 2

Inspected: 04/07/2015



Pit looking east. Tire tracks indicate the public accesses the site.



Pit looking north west. Pit walls are stable- no erorsion.



Bottom pit looking northwest



Bottom pit/stockpile area.

